

## User Guide Change Summary

### OEM750/750X Drive /Indexer User Guide

---

**Revision B**  
**January 2000**

---

The following is a summary of the primary technical changes to this document since the previous version was released. This document, p/n 88-016109-01 **B**, supersedes 88-016109-01 **A**.

#### **New OEM750X Features**

*New features* — Software flow control, device ID string, communication error checking, and RS-485 option have been added to the OEM750X. See Software Reference Guide, p/n 88-013785-01 Rev C or higher (NOTE: This only applies to firmware 92-016638-01).

#### **Speed/Torque Information (pg 48)**

*Clarification* — Parallel connected motors are limited to 50% duty cycle when operated above 5 rps. For greater than 50% duty cycle above 5 rps, you must connect the motor in series. Fan cooling the motor will increase duty cycles above 5 rps.

*Clarification* — Allow +/- 10% torque tolerance due to motor tolerance.